



Bus Giant | 534 New York Ave., Huntington, NY 11743  
Contact: Local Sales Representative | (888) 800-3779 | jhayes@busgiant.com

**Stock #: 6034DD**

## Description

- 2020 Stallion - Double Decker DD6109GS
- Body: Double Decker
- Length:
- Capacity: 47
- Engine: CUMMINS ISL 330 9L Diesel
- Colour: None
- Status: Used

**Price: \$0.00**



## Features / Options

CP = Co-Pilot Seat | LR = Luggage Rack | PS = Perimeter Seating | RR = Rear Ramp | RS = Rear Storage (no wall) | RSW = Rear Storage with Wall | WS = Wheelchair Station

### Chassis Features

- Engine: USA CUMMINS ISL 330 9L diesel engine (330hp, EPA2015) with engine compartment extinguisher system and two inspecting lights; After-treatment and DEF. Max torque/ rpm: 1100@1300 EPA 2016
- Comes with a one year warranty from CUMMINS
- Propeller shaft: Strengthened propeller shaft
- Axle: Front ZF disc axle with kneeling ZF rear disc axle.
- Suspension: ZF air suspension, air bellows. ECAS system. Dual circuit direction shock absorber
- Steering: ZF8098 power steering gear
- Braking: Front disc brakes with Bendix ABS. rear disc brake driving axle Dual circuit service braking system; Energy storage spring parking brake;
- Tires: Michelin 275/70R22.5 tubeless tire with Aluminum Alcoa Rims
- Import automatic slack adjuster
- Bendix air-operated system
- VDO water temperature sensor
- VDO oil pressure sensor
- Imported flash relay and general relay
- Advanced fuel sensor
- Chief circuit with easy inspection components
- Imported electromagnetic valve for door pump

### Safety

- Luxury rear-view mirror with defroster
- MEKRA LANG electric rear-view mirror with defroster
- Front windshield with defroster
- Front window double electric sunvisor
- Remote control passenger door lock
- Reverse camera integrated with the G-BOS system
- Front and rear LED destination board
- Backup Camera integrated with G-BOS
- Low entry structure

### Heating & Cooling

### Doors & Windows

- Front Single Piece Plug Style Door. Rear two pieces pneumatic swing in passenger door (double sealed). Stairwell to the upper deck behind the entry door
- Split Front windshield with defroster, One one-piece upper Windshield. Single-layer sealed side windows Dark color side glasses. Twelve pieces push out windows as emergency doors (upper and lower). 2 emergency exit roof w

### Electrical

- Long strip LED roof lamps. Step lamps; High-position braking lamp; LED aisle light, Exterior LED Lamps
- Reading lamp
- 7 cameras integrated with the G-BOS system 1. For the lower front door. 2. For the lower cabin. 3. For the front route. 4. For upper ladder. 5. For the front upper floor. 6. For rear upper floor. 7. Backup Camera

### Exterior Features

- Metallic paint
- Stainless body

### Entertainment

- AM / FM radio

- Front and rear door tow hook
- Dependant defrost system
- Energy Storage spring parking brake

- HERMO KING back-style air conditioner in cool and heat function. (lower only)
- SPHEROS Long stripe heater installed on the floor in 30000kcal

#### **Interior Features**

- Laminated bamboo or composite floor with anti-abrasion floor
- Stainless handrail
- Luxury interior decoration

#### **Miscellaneous**

- Luxury dashboard
- Garbage bin
- Front and rear towing hook

#### **Wheelchair Equipment**

- ADA Compliant with Wheelchair Lift